

# Industry & Facilities Division Third Party Inspection Report

Page 1 of 6

NSPECTION REPORT	Nr- BVL-40- 210415-01-R002-CM		Re	vision Nr		
☐ Initial ☐ Interim ☐ Fi	inal Resident					
	haddar Machinery Company					
nspection performed as Re	ecognised Authority:	Yes,:	$\boxtimes$	No		
3V Job Nr: 210415-01		<u> </u>				
Project:		IPO Ref (If app	licable):			
. ojooti		(BV internal P/o)				
BV Client:	P/o nr:	The state of the s				
Shaddar Machinery Compa	(client to BV)					
// // // // // // // // // // // // //	P/o nr:					
Shaddar Machinery Compa	(client to Manua	facturer)				
Sub-Vendor (If applicable)						
nspection Location:		ection (If applicat	ole):			
Ghaddar Factory - Ghazieh		(Date)				
nspection performed on:			n (If applicable):			
15/04/2021		(Date)				
MATERIAL / SUBJECT	OF INSPECTION	ITEM / TAG Nr	QTY	QTY		
HATERIAL / SUBJECT	OF INSPECTION	TI LIII / TAG IN	As per P/O	CONTRACTOR OF THE PARTY OF THE		
ПВ	efer to attachment section J instead			inspection		
	material list is provided in attachment)					
(malcate ii separate	material list is provided in attachmenty					
CT1250 genset po	owered by cummins KTA50G3	2021030244	1	1		
011,200 general						
A – INSPECTION RESU		Not Satisfact NCR raised durin				
nspection Summary:						
Refer to section E						
Open Non Conformities:		⊠ No				
Open Punch List Items:	☐ Yes, details in section H		⊠ No			
Release Note Issued:	Yes, number(s):		⊠ No			
Release Note Issued:	Tes, Hamber(e).					
BV Stamping:	Yes, Yes, Yes, Yes, Yes, W		□ No /			

This template is intended exclusively when BV is acting as 3° party inspection body. The use of present template is forbidden in the frame of 2° party services where Client specification and templates must be used.

## Industry & Facilities Division Third Party Inspection Report



Page 2 of 6

	BVL40- 210415-01-R00	2-CM			Revision Nr
BV Office:			ction Report	Date:	
Lebanon		20-04-2021			
Distribution:  CLIENT BV MANUFACTURER OTHER:			iments Repo		□ No
B - REFERENCE DOCUME		(Indicate if			ent section J inste
ISO 8528-6		(marouto ii			
ISO 8528-13				III Eliza	
C - ATTENDEES					
Name	Position		a saturate survive w	Represent	ing
Mr. Mohammad Shaat		Tele Service		Ghaddar	
D - MEASURING & TESTIN	G EQUIPMENT USED				
D - MEASURING & TESTING		(Indicate if			ent section J inste
			separate equip		
			separate equip	ment list is p	rovided in attachme
			separate equip	ment list is p	rovided in attachme
			separate equip	ment list is p	rovided in attachme
			separate equip	ment list is p	rovided in attachme
			separate equip	ment list is p	rovided in attachme
			separate equip	ment list is p	rovided in attachme
			separate equip	ment list is p	rovided in attachme
D - MEASURING & TESTING Equipment Type			separate equip	ment list is p	rovided in attachme
			separate equip	ment list is p	rovided in attachme

### **E-INSPECTION DETAILS**

GM-SI-101 INSP002-En Version 5.0

This template is intended exclusively when BV is acting as 3° party inspection body.



Copyright Bureau Veritas 05/2017



Page 3 of 6

#### INSPECTION REPORT Nr-BVL40- 210415-01-R002-CM

**Revision Nr** 

#### Description of the inspections carried out:

Bureau Veritas Liban surveyor witnessed the tests performed on one, CT1250 (1250 KVA) genset powered by cummins SN: 2021030244, based on ISO-8528-6 & 13.

The tests witnessing was performed on 15 April 2021. The document review was performed on 15 April 2021

The results of the witnessed tests are attached in appendix A

The submitted internal test reports for the alternator and engine are attached in appendix B. Those tests were not witnessed by Bureau Veritas Liban.

F – HEALTH, SAFETY & ENVIRO	(Comment on Observations and Actions Taken During the Inspection)
Non	
G- NON CONFORMITIES	Refer to attachment section J instead  (Indicate if separate punch list is provided in attachment)
None	
H - PUNCH LIST ITEMS	☐ Refer to attachment section J instead (Indicate if separate punch list is provided in attachment)
None	

I - DIGITAL PICTURES

BU

GM-SI-101 INSP002-En Version 5.0

Copyright Bureau Veritas 05/2017


This template is intended exclusively when BV is acting as 3° party inspection body.



### INSPECTION REPORT Nr-BVL40- 210415-01-R002-CM

**Revision Nr** 





Genset

Genset



Genset



During the testing



GM-SI-101 INSP002-En Version 5.0

This template is intended exclusively when BV is acting as 3° party inspection body.

Copyright Bureau Veritas 05/2017



#### INSPECTION REPORT Nr-BVL40- 210415-01-R002-CM

**Revision Nr** 





Genset




Genset

During the testing

During the testing







During the testing

GM-SI-101 INSP002-En Version 5.0

This template is intended exclusively when BV is acting as 3° party inspection body.

Copyright Bureau Veritas 05/2017

## Industry & Facilities Division Third Party Inspection Report



Page 6 of 6

#### INSPECTION REPORT Nr-BVL40- 210415-01-R002-CM

**Revision Nr** 

Item	Attachment Name	Total Pages	Description
1	Α	7	Witnessed tests report
2	В	2	Submitted reports

#### **END OF REPORT**



GM-SI-101 INSP002-En Version 5.0

This template is intended exclusively when BV is acting as 3° party inspection body.

Copyright Bureau Veritas 05/2017